



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

October 13, 2011

Reviewed: 

Mine Name: Tickaboo Stockpile Removal Project	Permit Number: S/017/0050
Operator Name: Ucolo Exploration	Inspection Date: October 5, 2011
Inspector(s): Wayne Western	Time: 11:30 – 11:50 AM
Other Participants: John Reay, BLM	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The permit fees have been paid and are current. The bond amount is \$10,000 and the renewal date is March 17, 2012.

The site is a stockpile of low grade ore. There are no shafts, adits or highwalls.


The site is stable and there were no signs of erosion.

There are no water impoundments on the site.

Conclusions and Recommendations:

The Division should continue to inspect the site on an annual basic.

Inspector's Signature

A handwritten signature in blue ink, appearing to read "John Reay", is written over a horizontal line.

WHW:

cc: (OPERATOR)


Sue Fivecoat BLM

John Reay, BLM

O:\M017-Garfield\S0170050-TicabooStockpileRemoval\inspections\INSP-10052011.doc



Stockpile looking north



Stockpile looking east